

Přehled limitovaných částí letounu:

Cirrus SR22 S/N: 22-3011 REG: OK-ROK	Operator: LETOV AIR Contact person: Ing. Václav Matoušek E-mail: letovair@letovair.cz Phone: 604232332	Total time (hrs): 608 Total cycles: 826 Date: 2019-01-07
---	---	---

Component:	PN:	SN:	Reference:	Action due:	Compliance			Performed			Next			Remaining		
					Ldgs:	Hours:	Years:	Ldgs:	Hours:	Date:	Ldgs:	Hours:	Date:	Ldgs:	Hours:	Months:
Airframe																
ARC				Renewal			1			2018-12-03			2019-12-03			11
Airframe 50 hrs	SR22			Inspection		50		826	608	2018-12-04		658			<u>50</u>	
Airframe 100 hrs	SR22	22-3011		Inspection		100	1	826	608	2018-12-04		708	2019-12-04	100		11
Insurance certificate				Renewal			1			2018-12-01			2019-12-01			11
Weight and Balance				weighing			6	826	608	2018-12-04			2024-12-04			71
CAPS Rocket motor assy				Replacement			10			2008-04-01			2018-04-01			<u>-9</u>
CAPS Parachute				Replacement			10			2008-04-01			2018-04-01			<u>-9</u>
CAPS Reefing Line cutters				Replacement			6			2008-04-01			2014-04-01			<u>-57</u>
Inflatable Restraint System	20902-001	23JAN08-84	Electronic Module Assy	Replace			14			2008-04-01			2022-04-01			39
Inflatable Restraint System			Electronic Module Assy	Refurbish			7			2018-10-31			2025-10-31			82
Inflatable Restraint System			Pilot seat inflator assy	Replacement			12			2008-04-01			2020-04-01			15
Inflatable Restraint System			Co-Pilot seat inflator assy	Replace			12			2008-04-01			2020-04-01			15
Cabin fire extinguisher				weighing			1	826	608	2018-12-04			2019-12-04			11
Battery 1	Gill G243	G03004073		Inspection		400	1	826	608	2018-12-04		1008	2019-12-04	400		11
Battery 2				Replace		500	2		605	2018-04-10		1105	2020-04-10	497		15
Gascolator Fuel Filter				Replacement			1	826	608	2018-12-04			2019-12-04			11
Brake assy O-rings			after SB2X-05-01	Replacement			5	826	608	2018-12-04			2023-12-04			59
Induction Air Filter	BA-24			Replacement		200	1	826	608	2018-12-04		808	2019-12-04	200		11
Induction Duct Flapper Bolt				Replacement		500	2	826	608	2018-12-04		1108	2020-12-04	500		23
Ice Protection System Filter	908-01		TKS Filter	Replacement		1200	2	826	608	2018-12-04		1808	2020-12-04	1200		23
Carbon Monoxide Detector				Replace			7	826	608	2018-12-04			2025-12-04			83
Fuel System Boost Pump	5217-00-9	7816		Replace			10	826	608	2018-12-04			2028-12-04			119
Evaporator Blower Motor				Replacement		5000				2008-04-01		5000			4392	
First aid kit				Check			1	826	608	2018-12-04			2019-12-04			11
First aid kit				Replacement			4			2018-10-31			2022-10-31			46
Avionics																
IFR check				Check			1	826	608	2018-12-04			2019-12-04			11
P/S system leakage				Test			1	826	608	2018-12-04			2019-12-04			11
Altimeters, Airspeed ind, Vario				Test			2	826	608	2018-12-04			2020-12-04			23
ELT Artex ME 406	453-6603			Test			1	826	608	2018-12-04			2019-12-04			11
ELT battery pack	455-0012		Artex ME406	Replacement			6			2013-09-30			2019-09-30			9
ELT Remote Control Battery				Replace			5	826	608	2018-12-04			2023-12-04			59
Compass swing				Check			1	826	608	2018-12-04			2019-12-04			11
Transponder				Check			2	826	608	2018-12-04			2020-12-04			23
Engine																

Engine	IO-550N (46)	691832	TCM	Overhaul		2000	12	826	608	2018-12-04		2608	2030-12-04		2000	143
Engine 50 hrs				Inspection		50		826	608	2018-12-04		658			<u>50</u>	
Engine 100 hrs				Inspection		100	1	826	608	2018-12-04		708	2019-12-04		100	11
Starter	C24ST5	H-S052518	Hartzell	Inspection		500		826	608	2018-12-04		1108			500	
Alternator 1	ES-10024	H-S092393	Hartzell	Overhaul		2000	12	826	608	2018-12-04		2608	2030-12-04		2000	143
Alternator 1				Inspection		500	2	826	608	2018-12-04		1108	2020-12-04		500	23
Alternator 2				Overhaul		2000	12	826	608	2018-12-04		2608	2030-12-04		2000	143
Alternator 2				Inspection		500	2	826	608	2018-12-04		1108	2020-12-04		500	23
Magneto LH	10-500556-1	D18M422G	Bendix	Overhaul		2000		826	608	2018-12-04		2608			2000	
Magneto RH	10-500556-1	D18M423G	Bendix	Overhaul		2000		826	608	2018-12-04		2608			2000	
Magneto LH				inspection/test		500	4	826	608	2018-12-04		1108	2022-12-04		500	47
Magneto RH				inspection/test		500	4	826	608	2018-12-04		1108	2022-12-04		500	47
Muffler and Heat Exchanger				Inspection		1000		826	608	2018-12-04		1608			1000	
Ignition Switch				inspection/test		2000		826	608	2018-12-04		2608			2000	
Fuel injection nozzles				Clean		300	5	826	608	2018-12-04		908	2023-12-04		300	59
Flexible Oil System Hoses			On Condition	Replacement												

Propeller

Propeller	PHC-J3YF-1RF	FP6621B	Hartzell	Overhaul		2400	6	826	608	2018-12-04		3008	2024-12-04		2400	71
Anti-Ice Propeller Boot				Replacement		2400	6	826	608	2018-12-04		3008	2024-12-04		2400	71
Propeller Governor	C290D3R/T23	071654	McCauley	Overhaul		2000	5	826	608	2018-12-04		2608	2023-12-04		2000	59
Propeller 100 hrs				Inspection		100	1	826	608	2018-12-04		708	2019-12-04		100	11

Recurring SB

SB2X-05-02			Induction duct flapper bolt	Replace		500	2	826	608	2018-12-04		1108	2020-12-04		500	23
SB2X-32-19 R3			NLG Inspection	Inspection		100		826	608	2018-12-04		708			100	